U.S. DEPARTMENT OF LABOR Occupational Safety and Health Administration

Form Approved OMB No. 44-R1387

MATERIAL SAFETY DATA SHEET

SECTION I				
MANUFACTURER'S NAME Aztec Chemical, Inc.		EMERGENCY TELEPHONE NO. (213) 448-9262		
ADDRESS (Number, Street, City, State, and ZIP Code) 212 S	. Turner Ave.	, West Covina, Ca. 91791		
		ANE AND WHOLING		
CHEMICAL FAMILY	FORMULA D	PM 5404-9330 Blue		

PAINTS, PRESERVATIVES, & SOLVENTS	%	TLV (Units)	ALLOYS AND METALLIC COATINGS	%	TLV (Unita)
PIGMENTS (contains no lead)	8	50	BASE METAL		
CATALYST			ALLOYS		
VEHICLE			METALLIC COATINGS		
SOLVENTS			FILLER METAL PLUS COATING OR CORE FLUX		
ADDITIVES			OTHERS		
OTHERS					
HAZARDOUS MIXTURES OF OTHER LIQUIDS, SOLIDS, OR GAȘES			%	TLV (Units)	
chlorinated hydrocarbon mixture			70	100	
(methylene chloride, perchloroethylene, trichloroethylene)					

SECTION III - PHYSICAL DATA				
BOILING POINT (°F.)	105	SPECIFIC GRAVITY (H20=1)	1.2	
VAPOR PRESSURE (mm Hg.)	150	PERCENT, VOLATILE BY VOLUME (%)	70	
VAPOR DENSITY (AIR=1) 3 EVAPORATION RATE (2		
OLUBILITY IN WATER not soluble				
APPEARANCE AND ODOR pigmented liquid, sweet odor				

SECTION IV - FIRE AND EXPLOSION HAZARD DATA					
FLASH POINT (Method used) none T.C.C.	FLAMMABLE LIMITS none	Lei	Uel		
compatible with dry, foam or Co					
SPECIAL FIRE FIGHTING PROCEDURES	ntained aspirators				
Would bout to	illuliidu abpirators				
UNUSUAL FIRE AND EXPLOSION HAZARDS					
none			·		

	070710	Alla	
THRESHOLD LIMIT V		NV - HEALTH HAZARD DATA	
EFFECTS OF OVEREX	POSURE.	. calculated	
	will burn eyes a	and irritate, defat the skin. Is toxic if swallowed.	
	est AID PROCEDURES eyes with large	amounts of water. Breathe fresh air if dizzy	
		give warm salt water and repeat until vomit is	
clear. Lie do	wn and cover eye	es. Immediately call a physician.	
Este St.	SECT	ION VI - REACTIVITY DATA	
STABILITY	JNSTABLE	CONDITIONS TO AVOID	
	STABLE X		
INCOMPATABILITY (A		xidizers	
HAZARDOUS DECOMPOSITION PRODUCTS			
	MAY OCCUR	exic fumes (conditions to Avoid	
HAZARDOUS POLYMERIZATION			
	WILL NOT OCCUR	x	
19 haqqaa taraanaa qabaqaya qayaddii isaa adalahay oo hahada haraada daada ah			
	SECTION V	/II - SPILL OR LEAK PROCEDURES	
STEPS TO BE TAKEN	IN CASE MATERIAL IS R		
soak and scoo	op up with an iner	rt filler. Dispose as hazardous paint waste	
WASTE DISPOSAL ME	THOD		
WASTE DISPOSAL ME	dispose	with approved incineration or permitted land fill	
	OF OTION VIII		
RESPIRATORY PROTE		SPECIAL PROTECTION INFORMATION	
		cartridge filter	
VENTICATION	LOCAL EXHAUST X	SPECIAL	
	MECHANICAL (General)	OTHER	
PROTECTIVE GLOVES	×	EYE PROTECTION X	
OTHER PROTECTIVE	electiv	е	
	CEATIA	AN IV OPPOLATION	
PRECAUTIONS TO BE	TAKEN IN HANDLING A	ON IX - SPECIAL PRECAUTIONS	
		s. Keep containers tightly sealed.	
OTHER PRECAUTION		s. Neep containers tightly sealed.	
	none		

PAGE (2)

GPO 934-110

Form OSHA-20 Rev. May 72